


**Upper Avenue Road Conservation Area Photographic Survey June 2010** 



## **Index of Photographs**

Upper Avenue Road Map	
1-3 Upper Avenue Road	
5 Upper Avenue Road	
7 Upper Avenue Road	8
9 Upper Avenue Road	9-10
11 Upper Avenue Road	11
13 Upper Avenue Road	12
15 Upper Avenue Road	13-14
17 Upper Avenue Road	15
19 Upper Avenue Road	
21 Upper Avenue Road	18-20
23 Upper Avenue Road	21-22
25 Upper Avenue Road	23
27 Upper Avenue Road	24
29 Upper Avenue Road	25-28
Crux Street unmade road reserve	29-30
31 Upper Avenue Road	31-32
33 Upper Avenue Road	33
35 Upper Avenue Road	34
37 Upper Avenue Road	35
39 Upper Avenue Road	36-37

### **Upper Avenue Road HCA**



### Introduction

#### Overview

This document provides a photographic record of buildings in The Upper Avenue Road Conservation Area (HCA), Mosman. This comprehensive record of the streetscape and built form can be used to benchmark and compare changes in The Upper Avenue Road Conservation Area over time.

# Statement of Significance for The Upper Avenue Road Heritage Conservation Area

The Upper Avenue Road Conservation Area is a rare example of an area without major interference by added street front garages, carports and privacy walls. It is a pleasing ensemble of mostly modest dwellings demonstrating very interesting variations of Federation styles as applied to unpretentious architecture.

### **Explanatory note**

Each page of this document contains a boxed key which, for each photograph, identifies

Street address

eg: 29 Upper Avenue Road

The street address for an individual building is identified in addition to the corner street if applicable. Streets, laneways and passages are also shown

Building title

eg:

The building title is identified from building façade signage

Heritage item Y/N

eg: N

Items of heritage significance are identified in Schedule 2 of the Mosman Local Environmental Plan 1998 and Schedule 5 of the Draft Mosman LEP 2008

HCA Ranking

eg: 1

The HCA Ranking (based on a scale of 1 to 4) has been identified from the Mosman Heritage Review 1996 (Godden Mackay Pty Ltd). A key to the conservation area ranking is provided below.

### Other comments

ie: Semi-detached

Other comments provide additional information of interest. For example, may state that the building is semi-detached or part of a series of photos taken to catch some detail otherwise not shown in one photograph

### Date of photograph

ie: 11 June 2010

The date the photograph was taken is indicated. Due to obstruction by traffic, weather or other constraints photographs were taken on various days through June and July 2010.

### **Extract from the Mosman Heritage Review 1996**

The following is an extract from the Mosman Heritage Review 1996 (Godden Mackay Pty Ltd), pages 91-92 of the main report. It is a key to the conservation area rankings (based on a ranking scale of 1 to 4) for each building identified in this photographic survey.

Ranking	Description	Objectives of
		development control
*	A building recommended for individual	Maintain heritage
	heritage listing in the heritage schedule	characteristics and
		streetscape intactness
1	A building with a high degree of intactness	Maintain heritage
	which contributes to the character of the	characteristics and
	area in the terms given in the definition of a	streetscape intactness
	Conservation Area	
2	A building which contributes to the character	Reconstruct original
	of the area but whose significance has been	features by removing
	reduced by loss of original materials or	unsympathetic additions or
	detail (e.g. roofs, chimneys, fences),	using more appropriate
	unsympathetic additions (e.g. verandah	decorative treatment
	infill) or inappropriate decorative treatment	
	(e.g. painting of face brickwork).	
3	A building whose impact on the heritage	Maintain benign impact
	character of the area is neutral	
4	A building which has an adverse impact	Encourage the ultimate
	upon the area because of its scale, design,	replacement of the building
	assertiveness, materials or the like, or	with one less assertive, or
	because its original qualities have been	amelioration of its adverse
	mutilated or removed	impact by sympathetic
		alterations, plantings, more
		appropriate colour scheme
		or other treatment



1-3 Upper Avenue Road Street address

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph


N 2/1 Photo 1 of 3 Semi-detached 11 June 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments

N 2 Photo 2 of 3 Semi-detached

Date of photograph 30 June 2010



3 Upper Avenue Road Merrels

Street address
Building title
Heritage item Y/N
HCA ranking
Other comments Ν

Photo 3 of 3 Semi-detached


Date of photograph 30 June 2010



Street address 5 Upper Avenue Road Keithville


Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν 2

11 June 2010




Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph 1

11 June 2010




Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph 2 House 4 Fence Photo 1 of 2 21 May 2010



Ν

Street address
Building title
Heritage item Y/N
HCA ranking
Other comments 2 House 4 Fence Photo 2 of 2 Date of photograph 30 June 2010




Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν 1

11 June 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν

Photo 1 of 2 21 May 2010



15 Upper Avenue Road Street address

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν


Photo 1 of 2 6 July 2010



Street address
Building title
Heritage item Y/N
HCA ranking Ν

Other comments

Date of photograph Photo 2 of 2 21 May 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν 1

11 June 2010




Ν

Street address
Building title
Heritage item Y/N
HCA ranking
Other comments 1 House 4 Fence Photo 1 of 2 Date of photograph 6 July 2010




1 House 4 Fence

Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Photo 2 of 2 6 July 2010




Street address

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Photo 1 of 3 30 June 2010




Street address

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Photo 2 of 3 30 June 2010



21 Upper Avenue Road Raywood N


Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Photo 3 of 3 21 May 2010



Street address 23 Upper Avenue Road

Ν 1

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Photo 1 of 2 6 July 2010



23 Upper Avenue Road Street address

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν


Photo 2 of 2 6 July 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph


N 2

21 May 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments N 2

21 July 2010 Date of photograph



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν


2 Photo 1 of 4 21 May 2010



Street address 29 Upper Avenue Road


Ν

Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph 2 Photo 2 of 4 30 June 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν


2 Photo 3 of 4 11 June 2010



Street address 29 Upper Avenue Road, showing side elevation to Crux Street unmade road reserve

Building title Heritage item Y/N HCA ranking Other comments Ν

2 Photo 4 of 4 Date of photograph 11 June 2010



Street address Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph

Crux Street unmade road reserve, looking south east


Υ

Photo 1 of 2 11 June 2010



Street address Crux Street unmade road reserve and Council retaining wall looking south east Building title Heritage item Y/N HCA ranking Other comments Υ


Photo 2 of 2 Date of photograph 21 May 2010




Street address 31 Upper Avenue Road, showing side elevation to Crux Street unmade road reserve

Building title Heritage item Y/N HCA ranking Other comments Ν

2 Photo 1 of 2 Date of photograph 11 June 2010




Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph N 2 Photo 2 of 2 11 June 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν 1

6 July 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph N 1

30 July 2010




Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν 1

30 July 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments
Date of photograph Ν Not ranked Photo 1 of 2 6 July 2010



Street address
Building title
Heritage item Y/N
HCA ranking
Other comments Date of photograph

Ν

Not ranked Photo 2 of 2 30 July 2010